

General Environmental Incident Summary

Incident: 933 **Date/Time Notice:** 6/13/2007 0842 **DEM Incident No:**
Responsible Party: Agriliance, LLC
Date Incident: 6/13/2007 **Time Incident:** 0700 **Duration:** 9 hours
County: Burleigh **Twp:** 138 **Rng:** 80 **Sec:** 12 **Qtr:**
Lat: 46.78733 **Long:** -100.72070 **Method:** Derived from TRS
Location Description: 1505 South Yegen Road, Bismarck

Submitted By: John Howe **Affiliation:**
Address:
City: **State:** **Zip:**

Received By: Brad Torgerson
Contact Person: John Howe
1505 South Yegen Road
Bismarck, ND 58502

Distance Nearest Occupied Building: 1000 Feet

Type of Incident: tank leak

Description of Released Contaminant: 32-00 liquid fertilizer

Volume Spilled: 25.00 gallons **Ag Related:** Yes

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

Hair line crack developed in the fertilizer tank/wagon sometime after being filled.

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Impacts to soils only at this time.

Action Taken or Planned:

The impacted soil will be removed with a Bobcat.

Wastes Disposal Location: The impacted soil will be land applied at appropriate agronomic rates.

Agencies Involved:

